

To Access PCS Database For KPDES information

Go to EPA's Envirofacts PCS Query Form

http://www.epa.gov/enviro/html/pcs/pcs_query_java.html

**In the Facility Selection portion, under Facility ID, choose NPDES.
Type the Facility ID in the box (example: KY0099821), select
*beginning with***

Under the Search Values portion, select *Use PCS facility info only*

Under the Output Selection portion, select *Permitted Discharge Info*

Click on *Search*

**On the output screen click on the NPDES Facility # (example click on
KY012083).**

Under Facility Information, select:

Facility

Inspections

Measurements and Violations

Outfall/Pipe Schedule

Compliance Schedule and Violations

Limits (select short format)

Click on *Search*

To Determine KPDES Number for Permitted Facility

**You will need the KPDES number for the permitted facility to obtain the
information in PCS.**

**If you have GIS software you can download the KPDES Permitted Facilities
layer from the Kentucky Geography Network**

<http://kygeonet.ky.gov/geographicexplorer/explorer.jsf> . This layer contains

the KPDES number within the Table of Attributes under the heading “KPDES”.

If you do not have GIS software you can obtain the information from the Watershed Viewer <http://eppcmaps.ky.gov/website/watershed/viewer.htm> .

Use the Zoom In tool to focus in on the area of interest. The Zoom In tool is the magnifying glass with + in center on the tool bar on the top of the screen. Left click on this Zoom tool, move the crosshairs to the area you want to enlarge and left click. Allow time for the program to retrieve the map of the closer view and then click the crosshairs again on the area of interest. Continue this process until the gray square to the left of the KPDES Permitted Facilities layer has a√. If there are any KPDES Facilities within the area they will appear as pink pentagons on the map.

Activate the KPDES Permitted Facilities layer by left clicking in the gray circle to the left of the layer.

Select the Identify tool on the top tool bar. The ID Visible Features tool is the red circle with i in the center on the tool bar on the top of the screen. Then move the crosshairs over the pink pentagon of the KPDES Facility of interest on the map and left click. The results for the selected KPDES Facility will appear below the map. The KPDES number is under the heading “KPDES”.